

IN THE DRAWINGS

Corrected drawings are supplied herewith.

The drawings were objected to because in Fig. 1 the reset is labeled 24 while in the specification the reset is labeled 26. The label in Fig. 1 has been as per the attached red-lined drawing.

The drawings were objected to for failing to comply with 37 CFR 1.84(p)(5) because they include the following reference sign(s) not mentioned in the description: ref. 108. Applicant was unable to find a reference number 108. A copy of Fig. 8 without the reference number 108 is attached.



RECEIVED

NOV 16 2004

Technology Center 2600




Fig. 1



RECEIVED

NOV 16 2004

Technology Center 2600





Fig. 8